□□□ □□□□

□□

□□□□□	KNA-125
□□□□	125g
□□□□□	A4□A3
□□□□	≥98□
□□□□	120□
□□□□□□□	□□□a-sub
□□□□□	100□□□/□□□
□□□□	30□□□/□□□□□A4□□□□

Printing Instructions

NOTE: For best results we recommend to use a transfer temperature of 205°C. Using this temperature will enhance the transfer quality.e.g.color densities and line sharpness.

Suggested Transfer Instruction

SUBSTRATES	TEMPERATURE	TIME	PRESSURE
Metal Plates	401F (205°C)	150±30 sec	Medium
Fiberglas	401F (205°C)	60±15 sec	Medium
Ceramic mugs	401F (205°C)	3±1 min	Heavy
Ceramic Tiles	401F (205°C)	6±1 min	Light-Medium
Plaques	401F (205°C)	60±15 sec	Medium
Hard boards	401F (205°C)	100±15 sec	Medium
Glass	401F (205°C)	5±1 min	Medium-Heavy
Mouse pads	401F (205°C)	60±15 sec	Medium
Textile applications	401F (205°C)	25-40sec	Medium

Please contact your substrate supplier for additional information

□□

□□□□□□□□□□□□□□□□□□□□□□□□□□□□□30□□□□□□□□□□□□□□□□□□□

Widely used in life